2016年6月16日

致

香港中區立法會道1號 立法會綜合大樓立法會秘書處 立法會交通事務委員會主席 田北辰議員

九龍巴士(一九三三)有限公司巴士網絡的新專營權事宜-新專營權公眾諮詢結果報告

為響應上述公眾諮詢·我們於2016年4月18日向政府提交一份意見書·針對巴士安全的持續改善·內容包括安全管理系統及一系列具體課題。

政府提交立法會交通事務委員會的文件 CB(4)1124/15-16(05)《九龍巴士(一九三三)有限公司巴 士網絡的新專營權事宜-新專營權公眾諮詢結果報告提供的文件》只有兩點關於安全的的簡單 敘述·分別為「更嚴格監察巴士車長的駕駛行為」及「改善車廂內的安全設施」。我們認為這樣 遠遠未能確實反映諮詢意見書涵蓋的觀點。

由於巴士安全是非常重要的課題·我們在此將諮詢意見書的原文(只有英文版)直接提交立法 會交通事務委員會作為參考。

此致,

鄺子憲 道路安全研究小組主席 (已簽署)

16 June 2016

The Chairman LegCo's Panel on Transport Legislative Council Secretariat, Legislative Council Complex 1 Legislative Council Road Central, Hong Kong

Attention : Hon. Tien Pak-sun Michael

Dear Legislative Council Members,

Administration's Paper on New Franchise for Bus Network of the Kowloon Motor Bus Company (1933) Limited - Report on The Public Consultation on the New Franchise

In response to the above public consultation, we submitted a document to Government on 18 April 2016. Our comments focus on continuous safety improvement for bus operation. The contents cover a safety management system in conjunction with a series of specific topics.

The document submitted by Government to LegCo's Panel on Transport CB(4)1124/15-16(05) "Administration's paper on new franchise for bus network of the Kowloon Motor Bus Company (1933) Limited - report on the public consultation on the new franchise" only consists of a short paragraph on safety with two simplified points, namely "to monitor bus captains' driving behaviour more closely" and "to improve safety facilities on buses". These clearly fail to reflect the much broader issues we raised.

Bus safety is a very important topic. For this reason we consider that it is necessary to submit our original document directly to LegCo's Panel on Transport for reference.

Yours faithfully,

Julian TH Kwong (signed) Chairman, Community for Road Safety

New Franchise for Bus Network of The Kowloon Motor Bus Company (1933) Limited

Comments

Overview

This paper provides recommendations to further improve the safety performance of Kowloon Motor Bus Company (1933) Limited (KMB) under the new franchise.

Cl. 4 of the consultation document by Government states that "The Government's key consideration in granting or extending a bus franchise is whether a grantee is capable of providing a proper and efficient bus service".

We believe that "Safety" must also be included as a primary objective.

It is agreeable that KMB has been providing generally satisfactory service and has become increasingly serious with safety. There are many good aspects of KMB's operation e.g. modern bus fleets, maintenance standard, drivers' training program. Cl. 8 of the consultation document cited KMB's efforts to improve safety with respect to drivers' rest time, health checks, speed limiters and black boxes. While these are all relevant and appreciated, many casualties could still be reasonably preventable. It is important not to miss the opportunities to further enhance KMB's safety performance with the new franchise.

Road Safety is of Paramount Importance

Cl. 6 (c) of the document indicates that KMB's accident rate was 2.95 accidents per million veh-km which is lower than 4.16 of the overall industry performance. While this indicates better overall performance of KMB, we consider it grossly inadequate to look at a single parameter i.e. accident rate per million veh-km, to conclude on KMB's safety performance. Due to the scale of its operation, KMB accounts for more than half of the bus-related casualties. This justifies a major effort to further bring down the casualty toll.


It will be necessary to analyse the number and rates of KMB buses involved in fatal and serious accidents, pedestrian accidents, multi-casualty accidents etc from a much wider perspective. It is also important to identify and address any major safety risks involving KMB's operation.

Rear-front and Junction Collisions

Given the prevalence of bus routes using high speed roads and expressways, KMB buses are particularly susceptible to rear-front collisions involving multiple casualties. During the three year period 2011 to 2013, there were over 40 multi-casualty crashes each with 5 or more casualties involving KMB buses. Historically, a single event with more than 100 casualties has been recorded. Such collisions could lead to very severe casualties especially for passengers taking up certain seats e.g. upper floor front row. Furthermore these events often put enormous strain on the emergency and medical service. Nevertheless, such events would only be classified as a single accident and therefore their severity cannot be reflected in the accident rate. In July 2015 alone, there were at least three multi-casualty collisions involving KMB buses resulting in 45 casualties.



Aftermath of a rear-front collision on an expressway



Passengers losing balance

Our estimate from accident data is that some 1,000 KMB occupants are injured every year. Some of these are due to collisions and some are due to passengers losing balance. The number of KMB passenger casualties due to losing balance or boarding/alighting a bus is in the order of 300-400 per year and the number of serious injuries is in the order of 40 to 50 with fatalities in the order of one per year. Furthermore, it is likely that many casualties went unreported. Presumably elderly persons are most susceptible to these accidents, yet Hong Kong is expecting an ever growing population of elderlies in the decades to come. These accidents need to be addressed systematically with meaningful targets of reduction.

Pedestrian Collisions

Our initial estimate also suggests that 70 to 80 pedestrians were knocked down by KMB buses every year. About 30% of these pedestrians sustained severe injuries. Over the three year period 2011 to 2013, twelve pedestrians died after being knocked down by KMB buses when crossing the road while a few died as a result of KMB buses crashing onto footpaths or losing control after a primary collision. Overall, pedestrians account for more than half of the fatal collisions involving a KMB bus. Irrespective of the circumstances of happenings and responsibility, this is not a trivial issue and certainly an area for improvement.

Overturning Accidents

Overturning of double decker bus could result in large number of fatalities and severe casualties. Such scenarios involving KMB buses continue to happen. This is unacceptable even though some of these happened with buses not in service for the general public.

- 9 November 2009 Tseung Kwan O
- 11 March 2011 Yuen Long
- 12 June 2015 Lung Cheung Road
- 8 February 2016 Yuen Long

Roadside Risks

Other than actual accidents, the safety of a bus carrying up to 130 passengers needs to be addressed from the perspective of risk. In this context we have been raising alert of the risk of buses falling off steep side slopes on highways. Our site inspections suggest that many steep side slopes, e.g. those along Clear Water Bay Road or Hiram's Highway, are not guarded or only lightly guarded by weak

safety barriers. These are grossly inadequate to stop a runaway bus from falling off the slopes. The consequences of a bus skidding or losing control at these locations would be disastrous with massive fatalities and casualties. Given the lack of recognition of this problem and very slow pace of road improvements, it would be up to the bus companies to compensate for the risks through education of their drivers and very stringent speed control when passing these highly risky road sections.



These rigid concrete bus stop canopies could destroy the entire upper deck of an errant double decker bus. Interim measures would include protocols requiring bus drivers to slow down as they exit from the high speed road

Recommendations

We recommend that past accident data and potential safety risks of bus operation are studied in detail, with a view of identifying opportunities for improvements under the new franchises. Government should take the lead to emphasize the importance of road safety of bus operation. The franchise requirements should incorporate these aspects in addition to proper and efficient service. Consideration could be given to rewarding the bus companies for achieving predefined goals, such as reduction of certain accident types by 20% per year.

Bus Safety – Road Safety Management System

As pointed out earlier, there is every reason to address safety performance of bus companies from the perspective of both accident data and risks. It follows that a modern approach should be introduced. One of the most important recent developments for fleet safety management worldwide is ISO 39001 "Road Traffic Safety Management". This quality assurance system encourages fleet operators to be far more accountable and proactive in reducing accidents and risks.

Recommendations

- Under the new franchise requirements encourage the bus companies to adopt a more advanced road safety management system towards the ISO 39001 standard.
- Government shall collaborate with the bus companies to study bus accidents and risks in details, with the view of setting targets of accident reduction.

Bus Safety – Driving Standard

It would be fair to say that many public bus drivers are professionals and are performing reasonably well. However, this does not necessarily imply that risks have been minimised. Furthermore, a certain proportion of bus drivers do behave aggressively and dangerously contributing to undue risks. Cl. 8(d)

of the consultation document states that KMB has completed retrofit of speed limiters and black box. There is vast potential of using black box in buses but it is not clear how these are being used.

We wish to point out that the legal urban speed limit of 50km/h cannot be taken as the golden rule. Buses weigh 18 to 24 tonnes and have capacity in excess of 100 passengers. They need much longer braking distance and sharp braking to avoid a collision will risk injuries to passengers. In busy urban streets and risky road sections over steep side-slopes, speeds would need to be reduced to levels commensurate with safety risks.

As an example, buses overtaking a stopped vehicle can legally travel at 50km/h on a typical multi-lane urban street despite constrained sightlines and frequent crossing pedestrians. Such speeds are very risky and suggest a lack of understanding and regulation on the part of bus companies and Government. Providing an efficient service can never be an excuse for inappropriate speeds.

Recommendations

- Incorporate into franchise requirement the need to set up a comprehensive standard and driver monitoring system using the installed black boxes. Monitoring systems should be automated with streamlined procedures to educate and retrain drivers.
- Key monitoring controls are:
 - Acceleration and deceleration characteristics (refer to extract below from the British Columbia Transit Infrastructure Design Guidelines) – crucial to problem of passengers losing balance.
 - Speed through risky hilly roads e.g. 25-40km/h through known hazardous sections or points– crucial to prevention of disastrous events.
 - Speed through urban areas e.g. 20-35km/h generally on busy urban streets – crucial to pedestrian and general safety.
 - Speed passing stopped vehicles/buses on urban streets e.g. 20-30km/h with adequate lateral separation to minimize risk with pedestrians coming out from gaps.
 - Speed through bus terminus e.g 15km/h or lower in compact bus termini.
 - Tailgating
 - Driving behind and around bicycles
- Through systematic and targeted safety training, drivers should be trained to understand typical accidents scenarios and specific risks.

4.4 Vehicle Performance

Buses generally have lower **acceleration** and deceleration rates compared to passenger vehicles. The acceleration and deceleration rates of transit vehicles should be taken into consideration in the design of public road and transit facilities for passenger comfort and safety. This is further discussed in Sections 5.2 and 5.3.

The Canadian Transit Handbook (Canadian Urban Transit Association and Transportation Association of Canada) suggests the desirable rates as shown in Table 4.3. The maximum deceleration rate for emergency situations should only be considered for extreme conditions, such as to avoid a collision.

Table 4.3 Desirable Acceleration and Deceleration Rates for Bus

Maximum Rate	Standard Bus (m/s²)	Articulated Bus (m/s ²)
Acceleration	0.9	0.7 - 0.9
Deceleration (normal service)	1.1	1.1
Deceleration (emergency condition)	2.7	2.7

Extract from the British Columbia Transit Infrastructure Design Guidelines

Bus Safety – Bus fleets

KMB has been investing in new modern buses. It is well agreeable that these buses are comfortable and well designed. However, attention is still required for safety risks including:

- Upper deck front seats in the absence of any reasonable deformation zone, front row bus passengers could be crushed despite the use of safety belts. This is particularly important with the number of KMB buses using high speed roads.
- Straight stairways passengers are prone to falling down the stairway during acceleration.
- Seat belts Not all higher risk seats and not all buses are equipped with seat belts.
- Adjustable arm rests these are prone to causing injuries for passengers losing balance when hitting the installations.
- Any sharp pointing objects these are prone to causing injuries for passengers losing balance when hitting them.
- Bus door safety- this subject is given attention after recent incidents involving bus passengers breaking the glass door and falling off.

Recommendations

• Incorporate into franchise requirements issues to be studied and improved with timetable.

Bus Safety – Bus Stops

KMB has been providing bus shelters and in return given the privilege of advertising at bus stops. While bus shelters are generally welcome, the safety of bus stops needs far more attention. As an example, waiting passengers along bus stops on Lung Cheung Road are left exposed to heavy and fast moving vehicles. A single runaway vehicle will result in massive casualties.

Recommendations

• Incorporate into franchise requirement that bus companies will collaborate with Government to reduce the risk for waiting passengers at bus stops.

